DOCKET NO.: 333055US6SD

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Akira IKEZAWA

PATENT NO.: 7,408,436 GROUP: 2832

ISSUED: August 5, 2008 EXAMINER: MAI, ANH T.

FOR: COIL AND BOBBIN FOR COIL

REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a Request for Certificate of Correction in Serial Number 10/587,742, now U.S. Patent Number 7,408,436.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

Gregory J. Maier

Registration No. 25,599

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/08) Michael L. Gellner

Registration No. 27,256

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.:

7,408,436

DATED:

August 5, 2008

INVENTOR(S):

Akira IKEZAWA

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 6, line 35, change

"FIGS. 1A and 1B" to --FIGS. 11A and 11B--.

Col. 9, line 30, change "The" to --A--.

Col. 10, line 14, change "The" to --A--.

Mailing address of sender:

Patent No.

7,408,436

Customer Number

22850

No. of add'l copies @ .30 per page

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/02)